



Appendix 12.3

Site Visit Photographs

Appendix A-Site Visit Photos

Description	Photo
Entry to the site and overall topography	 A photograph showing the entry to a site. In the foreground, there is a paved area with a metal grate. To the right of the grate is a large bush with reddish-brown leaves. The middle ground is filled with tall, yellow wildflowers. In the background, there is a line of green trees, and behind them, several white wind turbines are visible against a cloudy sky. A small red brick building is partially visible on the left side of the image.

REPORT

'Pond' feature in northeast corner. Raised banks out of ground. Vegetation identified within the feature indicates water present at times



REPORT

Culvert
location on
OS
MasterMap.
Could not
get closer
due to
barbed wire



REPORT

Ditch seen along boundary. Approximately 1m wide and 0.5m deep. Dry at time of visit. Unclear in image.



REPORT

West area
of site.
Inaccessibl
e



REPORT

Culvert at
northwest
corner of
site –
estimated
to measure
200mm
diameter



REPORT

Culvert/outfall to the northeast of the site. Estimated as 200mm diameter

